

# Firmware Update REMINDER

## Model: B055-001-SER

In order for the B055-001-SER to function properly, your KVM switch must be running firmware version 1.0.075 or higher. The latest firmware can be found at [www.tripplite.com/support](http://www.tripplite.com/support).

### PROTECT YOUR INVESTMENT!

Register your product for quicker service and ultimate peace of mind.

You could also win an ISOBAR6ULTRA surge protector—a \$50 value!



[www.tripplite.com/warranty](http://www.tripplite.com/warranty)



1111 W. 35th Street, Chicago, IL 60609 USA • [www.tripplite.com/support](http://www.tripplite.com/support)

Copyright © 2014 Tripp Lite. All rights reserved.

14-06-173 • 93-3384